

# REPORT

## TRUESDAIL LABORATORIES, INC.



CHEMISTS - MICROBIOLOGISTS - ENGINEERS  
RESEARCH - DEVELOPMENT - TESTING  
ESTABLISHED 1931

14201 FRANKLIN AVENUE  
TUSTIN, CALIF. 92680  
(714) 730-6239 • (213) 225-1564  
FAX (714) 730-6462

CLIENT: Douglas Aircraft  
3855 Lakewood Blvd  
Long Beach, CA 90846  
ATTN: Michael Binder

REPORT DATE: Sept. 29, 1994

RECEIVED: Sept. 13, 1994

LABORATORY NUMBER: 70787

SAMPLE DATE: 09/13/94  
SITE ID: Torrance Stormdrain

### MONTHLY/QUARTERLY ANALYSIS AS REQUESTED

### RESULTS

pH, Units (150.1)  
Temperature, °F

8.20  
70

PARAMETER	METHOD	MILLIGRAMS PER LITER	
		DETECTION LIMIT	CONCENTRATION
Biochemical Oxygen Demand	405.1	2.0	23
Chromium, Total	200.7	0.01	ND
Oil & Grease	413.1	5.0	21.7
Settleable Solids	160.5	0.1 ml/L/hr	ND
Total Suspended Solids	160.2	4.0	11

\*ND = Not Detected, below detection limit



Respectfully Submitted,  
Truesdail Laboratories, Inc.

*Thomas Herrin*  
Thomas Herrin, Manager  
Environmental Field Services

This report applies only to the sample, or samples, investigated and is not necessarily indicative of the quality or condition of apparently identical or similar products. As a mutual protection to clients, the public and these Laboratories, this report is submitted and accepted for the exclusive use of the client to whom it is addressed and upon the condition that it is not to be used, in whole or in part, in any advertising of publicity matter without prior written authorization from these Laboratories.